



5106.109 - 2018022880
Bogotá, 28 de mayo de 2018

Señor:
Gustavo Moreno Serna
Director de Calidad
AVIANCA
AEROPUERTO EL DORADO HANGAR 1
BOGOTA

Asunto: Aceptación Boletín de servicio No. ATR72-25-1173 donde se referencia el boletín tecnico de Zodiac Aerospace No. 536-25-004. (EASA AD No.: 2016-0167R1):


Apreciado(a):


Nos permitimos informarle que una vez evaluada la documentación de solicitud de aceptación del Boletín de Servicio No. ATR72-25-1173, clasificado como Alteración Mayor, y relacionado en la Directiva de Aeronavegabilidad No. 2016-0167R1, emitida por la autoridad aeronáutica EASA, se emite concepto favorable a la misma y se procede a la publicación de la aceptación del Boletín de Servicio mencionado en la página WEB de la UAEAC

Numero	Descripción	Autoridad aeronáutica Civil (AAC) del Estado de diseño / Organización delegada	Fecha de emisión
2016-0167R1	Cases of corrosion and cracks were found on Zodiac Seats France CAS 536 rear cabin attendant seats installed on some ATR 42 and ATR 72 aeroplanes. The detected damage was located on the lower parts of the attendant seat, at the level of the seat-to-floor interface.	EASA	31 Agosto 2016

Nota: La aceptación del Boletín de Servicio se volverá de uso común para cualquier operador a quien le aplique el mismo.

Cordialmente,


José Orlando Daza
Inspector de Seguridad Aérea

Recibí 

Ruta electrónica: \\bog7\ADI\Externo\2018022880