

510210912-2012052223 Bogotá, December 28, 2012

Eng. Giuseppe Paduano Office of Airworthiness Costruzioni Aeronautiche TECNAM srl

Via Maiorise - 81043 Capua - Caserta (Italy)

Phone: +39 0823 620134; Fax: +39 0823 622899

e-mail: g.paduano@tecnam.com

Subject:

ACCEPTANCE PROCESS BY VALIDATION OF EASA

TC A.412 FOR AIRCRAFT P92JS (Engine Rotax 912S2

and Propeller Hoffman HO17GHM A 174 177C).

Reference No.: EASA application number 0010019934 for Validation of

EASA TC A.412, Aircraft P92JS.

Reference Date: November 12, 2012

## Other References:

- 1. Colombian Civil Aviation Regulations, RAC No. 9.1 and 9.2.3
- 2. Tecnam P92JS, EASA TC A.421.
- 3. Engine Rotax 912S2, Austrian TC TW 9-ACG & EASA TC E.121.
- Propeller Hoffman HO17GHM A 174 177C, LBA TC 32.110/1.

## Dear Sir.

According to your application for the acceptance of the EASA TC A.421 for the Tecnam P92JS, aircraft, with Rotax Engines 912S2 (Austrian TC TW 9-ACG & EASA TC E.121) and Propeller Hoffman HO17GHM A 174 177C (LBA TC 32.110/1), and considering that Costruzioni Aeronautiche TECNAM srl has submitted the requested documents, which were evaluated under Colombian Civil Aviation Regulations (RAC) and that the Colombian Civil Aviation Authority (UAEAC), has completed the EASA TC acceptance by validation, this authority welcomes the Tecnam P92JS, with the Engine and Propeller related in the references, to operate in Colombia. However, it is important to note that we will only accept the aircraft configuration, certification basis, as well as the airworthiness and operations limitations as stated in the EASA Type Certificate and the supplied documentation.

> Clave: GDIR-3.0-12-08 Version: 01 Fecha: 20/09/2011 Página: 1 de 2





Costruzioni Aeronautiche TECNAM srl will keep updated the continued airworthiness documents required to guarantee the proper operation in accordance with the recommendations of the State of Design and Certification. Any change of the information mentioned above, must be reported and documented to the Colombian Civil Aviation Authority (UAEAC).

If you have any questions, please do not hesitate to contact us.

Sincerely,

Eng. Jairo E./Salazar Flight Standards Director

Civil Aviation Authority of Colombia (UAEAC)

Attached:

TC Acceptance report, GSAC-4.0-8-02 TECNAM P92JS.

Copy to:

Files Type Certification

Carl Thomas (EASA General Aviation Section Manager), email: CSV@easa.europa.eu

Prepared by:

Eng. J. Daza / Eng. A. Gonzalez

Copy to:

Cr. (r) German Ramiro Garcia Acevedo, Air Safety Secretary

Ruta electrónica: \\bog7\ADI\Externo\2012052223