



Al contestar cite Radicado 2024240040062255 Id: 1578411
Folios: 2 Fecha: 2024-12-29 16:26:13
Anexos: 1 DOCUMENTOS ELECTRONICOS
Remitente: SECRETARIA DE AUTORIDAD AERONAUTICA
Destinatario: LEONARDO SPA

Bogotá, Colombia. December 12, 2024.

Mr.

Emanuele Bufano

Head of Airworthiness

Leonardo S.p.a. Helicopters

Piazza Monte Grappa 4. Roma, Italy.

Subject: Acceptance of EASA Type Certificate No. EASA.R.005 Issue 25 for model A109S Rotorcraft.

References:

1. EASA Letter EASA/60092555. EASA Task Number 60092555.
2. Leonardo S.p.a. Helicopters Letter reference No. AIRW/2024/043.
3. Colombian Aeronautical Regulations RAC 21.156.

Dear Mr. Bufano,

According to your application for the acceptance of EASA Type Certificate No. **EASA.R.005 Issue 25** applicable to model **A109S** Rotorcraft and considering that “Leonardo **S.p.a. Helicopters**” has submitted the required certification documents, which were evaluated under Colombian Civil Aviation Regulations RAC 21.156, the Colombian Civil Aviation Authority (AEROCIVIL) hereby accepts the mentioned EASA Type Certificate and welcomes the model **A109S** Rotorcraft to operate in Colombia.

Attached to this letter is the Type Certificate Acceptance Report, detailing all the supporting documents and the analysis performed by us in support of your request. Please be aware that any operator intending to operate this model in Colombia, must verify the helicopter is in compliance with the Type certificate, which can be shown by the issuance of an Export

Unidad Administrativa Especial de Aeronáutica Civil

www.aerocivil.gov.co - Av. El Dorado # 103 – 15 Bogotá, D.C., Colombia

Para radicaciones <https://aerocivilsgdea.com/ControlPQR>

Conmutador: (+57) 601 425 1000 - Línea WhatsApp: (+57) 317 5455847

Certificate of Airworthiness for the product. Also any operator must show that the operational requirements listed in the report attached (section 5 of the acceptance report) are in compliance, in order to obtain a Standard Airworthiness Certificate issued in Colombia per the requirements of RAC 21.825.

To guarantee the safe operation and support the continued airworthiness of the model A109S Rotorcraft registered in Colombia, "Leonardo S.p.a. Helicopters" should keep the Type Certificate documents updated.

Concerning the Post Type Validation procedure, AEROCIVIL will accept the EASA findings for all post-Type Validation changes to the Type Design (including design change approvals, Airworthiness Limitations (AWL) approvals, Service Bulletin (SB) approvals, and Continuing Airworthiness).

This letter of acceptance will remain valid until the original type certificate remains valid, unless EASA cancels or revokes the accepted type certificate, or the Type Certificate holder ("Leonardo S.p.a. Helicopters") voluntarily surrenders it to EASA.

Sincerely,



CR. (R) Rodrigo R. Zapata R.
Secretary of Aeronautical Authority
Colombian Civil Aviation Authority (AEROCIVIL)

Attachments: Type Certificate Acceptance Report EASA TYPE CERTIFICATE No. EASA.R.005 Issue 25. Leonardo S.p.a. Helicopters Model A109S

Copy: validation.support@easa.europa.eu

Prepared by: Jairo Sora Torres - Certification of Aeronautical Products Engineer



Revised by: David F. Muñoz Galeano - Chief Certification of Aeronautical Products Group



Unidad Administrativa Especial de Aeronáutica Civil

www.aerocivil.gov.co - Av. El Dorado # 103 - 15 Bogotá, D.C., Colombia

Para radicaciones <https://aerocivilsgdea.com/ControlPQR>

Conmutador: (+57) 601 425 1000 - Línea WhatsApp: (+57) 317 5455847